

5090
Ser 1146/HP/RWQCB/1tr
1 OCT 1987

Mr. Lester Feldman
State of California
California Regional Water Quality
Control Board
San Francisco Bay Region
1111 Jackson Street, Room 6040
Oakland, CA 94607

Dear Mr. Feldman:

We are in the process of developing Remedial Investigation/Feasibility Study (RI/FS) work plans for the characterization of hazardous waste contamination at Ex-Hunters Point Naval Shipyard, San Francisco, California to comply with the requirements of Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), as amended by Superfund Amendments and Reauthorization Act (SARA).

Before completing the proposed RI/FS work, we request the Regional Water Quality Control Board, San Francisco Bay Region identify any requirements, standards, criteria, and/or limitations which it believes are legally applicable or relevant and appropriate to the Navy's response to the hazardous substances at Ex-Hunters Point Naval Shipyard under CERCLA, as amended by SARA. In order to incorporate your input into our workplan please identify in writing such applicable or relevant and appropriate requirements, standards, criteria, and/or limitations by November 2, 1987.

In your written response please provide citations of authority for any requirements, standards, criteria, and/or limitations you identify which are contained in Federal and/or State law and/or regulations. In addition, please provide us with copies of documents which set forth any standards, criteria, and/or limitations which are not contained in Federal or State law or regulations.

Please direct your response to the following address:

Commander
Western Division
Naval Facilities Engineering Command
P.O. Box 727
San Bruno, CA 94066-0720

000
08L
08G
08H
08J
08K
08W
01
012
013
014
015
016
017
018
019
020
021
022
023
024
025
026
027
028
029
030
031
032
033
034
035
036
037
038
039
040
041
042
043
044
045
046
047
048
049
050
051
052
053
054
055
056
057
058
059
060
061
062
063
064
065
066
067
068
069
070
071
072
073
074
075
076
077
078
079
080
081
082
083
084
085
086
087
088
089
090
091
092
093
094
095
096
097
098
099
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200

21146 Had seen
21146
114663 098
21146

5090

Ser 1146/HP/DOHS/1tr

If you have any questions concerning this subject, the point of contact is
Commander, Western Division, Naval Facilities Engineering Command (Attn:
Mr. Alex E. Dong, Code 1146, (415) 877-7504).

Sincerely,

P. W. DRENNON
CAPTAIN, CEC, USN
COMMANDER

WRITER: G. Brown/1146GB/7504
TYPIST: B. Palmer/16 Sep 87/Ser 3140h
FILE: HP/DOHS/1tr

00

08

08L

08C

08G

08J

08K

08W

01

012

013

016

08A

08A1

08A2

02

04

05

08B

08

10

11

09P

20

24

08R